

Bas. start date	Basic fin. date	Sort field	Description
04/10/2013	04/10/2013	TKM06	13W Mech Svce Truck TKM06
11/11/2013	11/11/2013	TKM06	TKM6 oil leak / dipstick
22/11/2013	22/11/2013	TKM06	TKM6 Both Radios not working
28/11/2013	28/11/2013	TKM06	TKM6 Handbrake needs adjustment.
10/12/2013	10/12/2013	TKM06	TKM6 - hand brake fault
20/01/2014	20/01/2014	TKM06	TKM06 Spare handheld radio installation
13/02/2014	13/02/2014	TKM06	13W Mech Svce Truck TKM06
13/02/2014	13/02/2014	TKM06	TKM 6 front coupler u/s
13/02/2014	13/02/2014	TKM06	TKM06 Bell Not working Properly
06/03/2014	06/03/2014	TKM06	TKM6 air & oil leak
21/05/2014	23/05/2014	TKM06	52W Mech Svce Truck TKM06
23/05/2014	23/05/2014	TKM06	TKM6 front side shift ram leak
26/05/2014	26/05/2014	TKM06	TKM 06 ISSUES
04/07/2014	04/07/2014	TKM06	13W Mech Svce Truck TKM06
05/09/2014	05/09/2014	TKM06	TKM6 leaking ram seals
23/09/2014	23/09/2014	TKM06	13W Mech Svce Truck TKM06
23/01/2015	23/01/2015	TKM06	13W Mech Svce TKM06
05/02/2015	05/02/2015	TKM06	TKM06 Engine Shutting Down
20/02/2015	20/02/2015	TKM06	TKM6 Emergency cut off switch faulty
14/04/2015	16/04/2015	TKM06	52W Mech Svce Truck TKM06
17/04/2015	17/04/2015	TKM06	TKM6 - tachometer faulty
17/04/2015	17/04/2015	TKM06	TKM06 Out of Service
24/04/2015	24/04/2015	TKM06	TKM06 air compressor not functioning
31/05/2015	31/05/2015	TKM06	TKM6 replace VHF Radio
03/07/2015	03/07/2015	TKM06	13W Mech Svce Truck TKM06
01/10/2015	01/10/2015	TKM06	13W Mech Svce Truck TKM06
06/11/2015	06/11/2015	TKM06	TKM1 Steering Cyl-Fit to TKM-6
08/12/2015	08/12/2015	TKM06	13W Mech Svce Truck TKM06 (BOODARIE PIT)
21/02/2016	21/02/2016	TKM06	TKM06 Replace air compressors
03/04/2016	29/06/2016	TKM06	TKM6 Fit Coupler Indicating Light
23/05/2016	25/05/2016	TKM06	52W Mech Svce Truck TKM06 (SES)
24/05/2016	24/05/2016	TKM06	TKM-06 Low Bateriaes Not Starting
28/06/2016	28/06/2016	TKM06	13W Mech Svce Truck TKM06
25/07/2016	25/07/2016	TKM06	TKM06 Engine solenoid not working
28/09/2016	28/09/2016	TKM06	TKM06 Front Coupler Release Pin Sticky
28/09/2016	29/09/2016	TKM06	13W Mech Svce Truck TKM06
03/10/2016	03/10/2016	TKM06	TKM06 Front Coupler Damaged
06/10/2016	06/10/2016	TKM06	TKM06 - WONT GO INTO GEAR
09/10/2016	09/10/2016	TKM06	TKM6 fit rear coupler indicating light
06/11/2016	06/11/2016	TKM06	TKM06 Refit drive tyre cylinder.
01/01/2017	01/01/2017	TKM06	TKM06 Fit Proxy switch to cylinder.
01/01/2017	01/01/2017	TKM06	13W Mech Svce Truck TKM06
06/01/2017	06/01/2017	TKM06	TKM06 Headlights and Beacon Not Working
31/01/2017	31/01/2017	TKM06	TKM06 Brake/Eng Oil Leaks/Over Temp
16/03/2017	16/03/2017	TKM06	TKM06 proximity switch broken
28/03/2017	28/03/2017	TKM06	TKM 06 Proximity switch broken
28/03/2017	29/03/2017	TKM06	TKM06 - Engine Idle Problem
31/03/2017	01/04/2017	TKM06	TKM06 Rear Wheel Hy Rail Seals Leaking

31/03/2017	31/03/2017 TKM06	TKM06 Guard Rails Missing Gates
31/03/2017	31/03/2017 TKM06	TKM06 Fuel Filter Replacement
02/04/2017	02/04/2017 TKM06	TKM06 hydraulic wheel cylinder leaking.*P
03/04/2017	03/04/2017 TKM06	TKM06 Electrical fault stuck on track
07/04/2017	07/04/2017 TKM06	TKM06 - FABRICATE GATE
12/04/2017	12/04/2017 TKM06	TKM06 - INSTALL 65L FIRE SUPPRESSION SYS
09/05/2017	09/05/2017 TKM06	TKM06 Replace alternator
09/05/2017	09/05/2017 TKM06	TKM06 Main Engine Batteries Flat
10/06/2017	13/06/2017 TKM06	52W Mech Svce Truck TKM06
11/06/2017	11/06/2017 TKM06	TKM06 Leaking Brake Caliper
30/06/2017	30/06/2017 TKM06	13W Mech Svce Truck TKM06
30/08/2017	30/08/2017 TKM06	TM06 fault troubleshooting GMc
17/09/2017	17/09/2017 TKM06	SES - TKM06 Deliver To TMWS WK37
18/09/2017	18/09/2017 TKM06	TKM06 Oil Pressure Switch Fault
18/09/2017	18/09/2017 TKM06	TKM06 Alternator pulley replacement
18/09/2017	18/09/2017 TKM06	TKM06 Fan belt replacement
18/09/2017	16/10/2017 TKM06	TKM06 - DRIVE TYRES WORN CHANGE OUT
18/09/2017	18/09/2017 TKM06	TKM06 Engine Won't Start
20/09/2017	20/09/2017 TKM06	TKM06 Float Back to MOCRS
13/10/2017	13/10/2017 TKM06	TKM06 Replace Engine Starter Motor
13/10/2017	13/10/2017 TKM06	13W Mech Svce Truck TKM06
17/10/2017	17/10/2017 TKM06	TKM06 Broken Coupler Indicator Proxy
20/10/2017	20/10/2017 TKM06	TKM06 - PARK BRAKE NOT ENGAGING
31/12/2017	31/12/2017 TKM06	TKM06 Park Brake Shoes Worn
02/01/2018	02/01/2018 TKM06	13W Mech Svce Truck TKM06
03/01/2018	03/01/2018 TKM06	TKM06 Fire suppression out of date
21/03/2018	21/03/2018 TKM06	TKM06 Continually Stalling
02/04/2018	03/04/2018 TKM06	52W Mech Svce Truck TKM06
04/04/2018	04/04/2018 TKM06	TKM06 Adjust valve clearances
13/04/2018	13/04/2018 TKM06	TKM06- Replace damaged proxy
17/06/2018	17/06/2018 TKM06	TKM06 air con not cooling
28/06/2018	28/06/2018 TKM06	TKM6 Continually Stalling
27/07/2018	27/07/2018 TKM06	TKM06 - TRANS/HYD OIL TYPE
29/07/2018	29/07/2018 TKM06	250H Mech Service Track Mobile 6
28/12/2018	28/12/2018 TKM06	TKM6 Remove Tyres